[BIOREACTORS/RATE_OF_CHANGE] - Control Studio

File Edit View Object Diagram Layout Tools Graphics Window Help

100%

Filtered by:

Alphabetic | Categorized

Parameter	Default
Alarm	
ABNORM_ACTI...	
ALARM_HYS	0.5
BAD_ACTIVE	
BAD_MASK	
BLOCK_ERR	
HI_ACT	0
HI_HI_ACT	0
HI_HI_LIM	100
HI_LIM	95
INSPECT_ACT	0
LO_ACT	0
LO_LIM	0
LO_LO_ACT	0
LO_LO_LIM	0
Operating	
FIELD_VAL	0
MODE	Auto/
OUT	0
PV	0
STDEV	0
STDEV_TIME	0
I/O	
IO_IN	
IO_OPTS	
OUT_SCALE	0.0 to 10..
SIMULATE_IN	0
XD_SCALE	0.0 to 10..
Tuning	
L_TYPE	Indirect
LOW_CUT	0
PV_FTIME	0
SIMULATE	Disabled,
STATUS_OPTS	
Misc	
STDEV_CAP	0



Analog Contrc

Bias/Gain

Calc/Logic

Control Selector

Deadtime

Fieldbus Inpu Selector Ext..

Filter

Input Selecto

Lead/Lag

Limit

For Help, press F1

Assigned to: <unassigned>