



Process Output (Y)
& Process Input (X)




Self-Regulating (Negative Feedback) Response

Process Output (Y)
& Process Input (X)



Integrating (Zero Feedback) Response



Runaway (Positive Feedback) Response